

Macho Máquina HSS SP-VA

Categorias

- INOX

Aplicação

Macho Máquina para Aço Inox - Furos Cegos



| Ref. | Descrição | D1 | D2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | Passo | Z | Tipo |
|-----------------|--------------------|----------|------|------|-----|----|----|----|----|-----|-----|-------|---|------|
| AB160SD4.0IAGEX | M4x0.7-D371-ISO2 | M4x0,7 | ISO2 | 2.5P | 63 | 7 | 13 | 21 | 38 | 4.5 | 3.4 | 6 | 3 | 371 |
| AB160SD5.0KAGEX | M5x0.8-D371-ISO2 | M5x0,8 | ISO2 | 2.5P | 70 | 9 | 14 | 25 | 39 | 6 | 4.9 | 8 | 3 | 371 |
| AB160SD6.0MAGEX | M6x1-D371-ISO2 | M6x1 | ISO2 | 2.5P | 80 | 11 | 15 | 30 | 45 | 6 | 4.9 | 8 | 3 | 371 |
| AB160SD8.0NAGEX | M8x1.25-D371-ISO2 | M8x1,25 | ISO2 | 2.5P | 90 | - | 12 | 35 | 47 | 8 | 6.2 | 9 | 3 | 371 |
| AB160SD010OAGEX | M10x1.5-D371-ISO2 | M10x1,5 | ISO2 | 2.5P | 100 | - | 13 | 39 | 52 | 10 | 8 | 11 | 3 | 371 |
| AB160SG012PAGEX | M12x1.75-D376-ISO2 | M12x1,75 | ISO2 | 2.5P | 110 | - | 15 | - | 56 | 9 | 7 | 10 | 3 | 376 |
| AB160SG016QAGEX | M16x2-D376-ISO2 | M16x2 | ISO2 | 2.5P | 110 | - | 18 | - | 56 | 12 | 9 | 12 | 3 | 376 |