


Fresa MD esf. 2MRB - 2Nav

Categorias

- Esféricas



| Ref. | Descrição | D1 | D3 | L1 | L2 | L3 | Raio | Z |
|-----------------|------------------|-----|----|----|-----|------|------|---|
| 27A600002005S04 | Ø 0.2x0.5x40-S04 | 0.2 | 4 | 40 | 0.5 | 0.3 | 0.1 | 2 |
| 27A600002010S04 | Ø 0.2x1x40-S04 | 0.2 | 4 | 40 | 1 | 0.3 | 0.1 | 2 |
| 27A600002015S04 | Ø 0.2x1.5x40-S04 | 0.2 | 4 | 40 | 1.5 | 0.3 | 0.1 | 2 |
| 27A600002020S04 | Ø 0.2x2x40-S04 | 0.2 | 4 | 40 | 2 | 0.3 | 0.1 | 2 |
| 27A600003010S04 | Ø 0.3x1x40-S04 | 0.3 | 4 | 40 | 1 | 0.45 | 0.15 | 2 |
| 27A600003020S04 | Ø 0.3x2x40-S04 | 0.3 | 4 | 40 | 2 | 0.45 | 0.15 | 2 |
| 27A600003030S04 | Ø 0.3x3x40-S04 | 0.3 | 4 | 40 | 3 | 0.45 | 0.15 | 2 |
| 27A600003050S04 | Ø 0.3x5x40-S04 | 0.3 | 4 | 40 | 5 | 0.45 | 0.15 | 2 |
| 27A600004020S04 | Ø 0.4x2x40-S04 | 0.4 | 4 | 40 | 2 | 0.6 | 0.2 | 2 |
| 27A600004030S04 | Ø 0.4x3x40-S04 | 0.4 | 4 | 40 | 3 | 0.6 | 0.2 | 2 |
| 27A600004040S04 | Ø 0.4x4x40-S04 | 0.4 | 4 | 40 | 4 | 0.6 | 0.2 | 2 |
| 27A600004050S04 | Ø 0.4x5x40-S04 | 0.4 | 4 | 40 | 5 | 0.6 | 0.2 | 2 |
| 27A600004060S04 | Ø 0.4x6x40-S04 | 0.4 | 4 | 40 | 6 | 0.6 | 0.2 | 2 |
| 27A600005020S04 | Ø 0.5x2x45-S04 | 0.5 | 4 | 45 | 2 | 1 | 0.25 | 2 |
| 27A600005040S04 | Ø 0.5x4x45-S04 | 0.5 | 4 | 45 | 4 | 1 | 0.25 | 2 |
| 27A600005060S04 | Ø 0.5x6x45-S04 | 0.5 | 4 | 45 | 6 | 1 | 0.25 | 2 |
| 27A600005080S04 | Ø 0.5x8x45-S04 | 0.5 | 4 | 45 | 8 | 1 | 0.25 | 2 |
| 27A600005100S04 | Ø 0.5x10x45-S04 | 0.5 | 4 | 45 | 10 | 1 | 0.25 | 2 |
| 27A600006020S04 | Ø 0.6x2x45-S04 | 0.6 | 4 | 45 | 2 | 1.2 | 0.3 | 2 |
| 27A600006040S04 | Ø 0.6x4x45-S04 | 0.6 | 4 | 45 | 4 | 1.2 | 0.3 | 2 |
| 27A600006060S04 | Ø 0.6x6x45-S04 | 0.6 | 4 | 45 | 6 | 1.2 | 0.3 | 2 |
| 27A600006080S04 | Ø 0.6x8x45-S04 | 0.6 | 4 | 45 | 8 | 1.2 | 0.3 | 2 |
| 27A600006100S04 | Ø 0.6x10x45-S04 | 0.6 | 4 | 45 | 10 | 1.2 | 0.3 | 2 |
| 27A600007040S04 | Ø 0.7x4x45-S04 | 0.7 | 4 | 45 | 4 | 1.4 | 0.35 | 2 |
| 27A600007060S04 | Ø 0.7x6x45-S04 | 0.7 | 4 | 45 | 6 | 1.4 | 0.35 | 2 |
| 27A600007080S04 | Ø 0.7x8x45-S04 | 0.7 | 4 | 45 | 8 | 1.4 | 0.35 | 2 |

| Ref. | Descrição | D1 | D3 | L1 | L2 | L3 | Raio | Z |
|-----------------|-----------------|-----|----|----|----|-----|------|---|
| 27A600007100S04 | Ø 0.7x10x45-S04 | 0.7 | 4 | 45 | 10 | 1.4 | 0.35 | 2 |
| 27A600008040S04 | Ø 0.8x4x45-S04 | 0.8 | 4 | 45 | 4 | 1.6 | 0.4 | 2 |
| 27A600008060S04 | Ø 0.8x6x45-S04 | 0.8 | 4 | 45 | 6 | 1.6 | 0.4 | 2 |
| 27A600008080S04 | Ø 0.8x8x45-S04 | 0.8 | 4 | 45 | 8 | 1.6 | 0.4 | 2 |
| 27A600008100S04 | Ø 0.8x10x45-S04 | 0.8 | 4 | 45 | 10 | 1.6 | 0.4 | 2 |
| 27A600008120S04 | Ø 0.8x12x45-S04 | 0.8 | 4 | 45 | 12 | 1.6 | 0.4 | 2 |
| 27A600009060S04 | Ø 0.9x6x45-S04 | 0.9 | 4 | 45 | 6 | 1.8 | 0.45 | 2 |
| 27A600009100S04 | Ø 0.9x10x45-S04 | 0.9 | 4 | 45 | 10 | 1.8 | 0.45 | 2 |
| 27A600009120S04 | Ø 0.9x12x45-S04 | 0.9 | 4 | 45 | 12 | 1.8 | 0.45 | 2 |
| 27A600010060S04 | Ø1x6x50-S04 | 1 | 4 | 50 | 6 | 2 | 0.5 | 2 |
| 27A600010080S04 | Ø1x8x50-S04 | 1 | 4 | 50 | 8 | 2 | 0.5 | 2 |
| 27A600010100S04 | Ø1x10x50-S04 | 1 | 4 | 50 | 10 | 2 | 0.5 | 2 |
| 27A600010120S04 | Ø1x12x50-S04 | 1 | 4 | 50 | 12 | 2 | 0.5 | 2 |
| 27A600010160S04 | Ø1x16x50-S04 | 1 | 4 | 50 | 16 | 2 | 0.5 | 2 |
| 27A600010200S04 | Ø1x20x60-S04 | 1 | 4 | 60 | 20 | 2 | 0.5 | 2 |
| 27A600010250S04 | Ø1x25x60-S04 | 1 | 4 | 60 | 25 | 2 | 0.5 | 2 |
| 27A600012060S04 | Ø 1.2x6x50-S04 | 1.2 | 4 | 50 | 6 | 2.4 | 0.6 | 2 |
| 27A600012080S04 | Ø 1.2x8x50-S04 | 1.2 | 4 | 50 | 8 | 2.4 | 0.6 | 2 |
| 27A600012100S04 | Ø 1.2x10x50-S04 | 1.2 | 4 | 50 | 10 | 2.4 | 0.6 | 2 |
| 27A600012120S04 | Ø 1.2x12x50-S04 | 1.2 | 4 | 50 | 12 | 2.4 | 0.6 | 2 |
| 27A600012160S04 | Ø 1.2x16x50-S04 | 1.2 | 4 | 50 | 16 | 2.4 | 0.6 | 2 |
| 27A600014060S04 | Ø 1.4x6x50-S04 | 1.4 | 4 | 50 | 6 | 2.8 | 0.7 | 2 |
| 27A600014100S04 | Ø 1.4x10x50-S04 | 1.4 | 4 | 50 | 10 | 2.8 | 0.7 | 2 |
| 27A600014160S04 | Ø 1.4x16x50-S04 | 1.4 | 4 | 50 | 16 | 2.8 | 0.7 | 2 |
| 27A600015060S04 | Ø 1.5x6x50-S04 | 1.5 | 4 | 50 | 6 | 3 | 0.75 | 2 |
| 27A600015100S04 | Ø 1.5x10x50-S04 | 1.5 | 4 | 50 | 10 | 3 | 0.75 | 2 |
| 27A600015140S04 | Ø 1.5x14x50-S04 | 1.5 | 4 | 50 | 14 | 3 | 0.75 | 2 |
| 27A600015160S04 | Ø 1.5x16x50-S04 | 1.5 | 4 | 50 | 16 | 3 | 0.75 | 2 |
| 27A600015200S04 | Ø 1.5x20x60-S04 | 1.5 | 4 | 60 | 20 | 3 | 0.75 | 2 |
| 27A600015250S04 | Ø 1.5x25x60-S04 | 1.5 | 4 | 60 | 25 | 3 | 0.75 | 2 |
| 27A600015300S04 | Ø 1.5x30x70-S04 | 1.5 | 4 | 70 | 30 | 3 | 0.75 | 2 |
| 27A600016060S04 | Ø 1.6x6x50-S04 | 1.6 | 4 | 50 | 6 | 3.2 | 0.8 | 2 |
| 27A600020080S04 | Ø2x8x50-S04 | 2 | 4 | 50 | 8 | 4 | 1 | 2 |
| 27A600020100S04 | Ø2x10x50-S04 | 2 | 4 | 50 | 10 | 4 | 1 | 2 |
| 27A600020120S04 | Ø2x12x50-S04 | 2 | 4 | 50 | 12 | 4 | 1 | 2 |
| 27A600020140S04 | Ø2x14x50-S04 | 2 | 4 | 50 | 14 | 4 | 1 | 2 |
| 27A600020160S04 | Ø2x16x50-S04 | 2 | 4 | 50 | 16 | 4 | 1 | 2 |
| 27A600020180S04 | Ø2x18x50-S04 | 2 | 4 | 50 | 18 | 4 | 1 | 2 |
| 27A600020200S04 | Ø2x20x60-S04 | 2 | 4 | 60 | 20 | 4 | 1 | 2 |
| 27A600020250S04 | Ø2x25x60-S04 | 2 | 4 | 60 | 25 | 4 | 1 | 2 |
| 27A600020300S04 | Ø2x30x70-S04 | 2 | 4 | 70 | 30 | 4 | 1 | 2 |
| 27A600020350S04 | Ø2x35x80-S04 | 2 | 4 | 80 | 35 | 4 | 1 | 2 |
| 27A600020400S04 | Ø2x40x80-S04 | 2 | 4 | 80 | 40 | 4 | 1 | 2 |

| Ref. | Descrição | D1 | D3 | L1 | L2 | L3 | Raio | Z |
|-----------------|-----------------|-----|----|-----|----|----|------|---|
| 27A600025120S04 | Ø 2.5x12x60-S04 | 2.5 | 4 | 60 | 12 | 5 | 1.25 | 2 |
| 27A600025200S04 | Ø 2.5x20x60-S04 | 2.5 | 4 | 60 | 20 | 5 | 1.25 | 2 |
| 27A600030080S06 | Ø3x8x70-S06 | 3 | 6 | 70 | 8 | 6 | 1.5 | 2 |
| 27A600030120S06 | Ø3x12x70-S06 | 3 | 6 | 70 | 12 | 6 | 1.5 | 2 |
| 27A600030160S06 | Ø3x16x70-S06 | 3 | 6 | 70 | 16 | 6 | 1.5 | 2 |
| 27A600030200S06 | Ø3x20x70-S06 | 3 | 6 | 70 | 20 | 6 | 1.5 | 2 |
| 27A600030250S06 | Ø3x25x70-S06 | 3 | 6 | 70 | 25 | 6 | 1.5 | 2 |
| 27A600030300S06 | Ø3x30x80-S06 | 3 | 6 | 80 | 30 | 6 | 1.5 | 2 |
| 27A600030400S06 | Ø3x40x90-S06 | 3 | 6 | 90 | 40 | 6 | 1.5 | 2 |
| 27A600030450S06 | Ø3x45x90-S06 | 3 | 6 | 90 | 45 | 6 | 1.5 | 2 |
| 27A600040120S06 | Ø4x12x70-S06 | 4 | 6 | 70 | 12 | 8 | 2 | 2 |
| 27A600040160S06 | Ø4x16x70-S06 | 4 | 6 | 70 | 16 | 8 | 2 | 2 |
| 27A600040200S06 | Ø4x20x70-S06 | 4 | 6 | 70 | 20 | 8 | 2 | 2 |
| 27A600040250S06 | Ø4x25x70-S06 | 4 | 6 | 70 | 25 | 8 | 2 | 2 |
| 27A600040300S06 | Ø4x30x70-S06 | 4 | 6 | 70 | 30 | 8 | 2 | 2 |
| 27A600040350S06 | Ø4x35x80-S06 | 4 | 6 | 80 | 35 | 8 | 2 | 2 |
| 27A600040400S06 | Ø4x40x80-S06 | 4 | 6 | 80 | 40 | 8 | 2 | 2 |
| 27A600040500S06 | Ø4x50x100-S06 | 4 | 6 | 100 | 50 | 8 | 2 | 2 |
| 27A600050160S06 | Ø5x16x80-S06 | 5 | 6 | 80 | 16 | 10 | 2.5 | 2 |
| 27A600050250S06 | Ø5x25x80-S06 | 5 | 6 | 80 | 25 | 10 | 2.5 | 2 |
| 27A600050350S06 | Ø5x35x80-S06 | 5 | 6 | 80 | 35 | 10 | 2.5 | 2 |
| 27A600060250S06 | Ø6x25x80-S06 | 6 | 6 | 80 | 25 | 12 | 3 | 2 |
| 27A600060350S06 | Ø6x35x80-S06 | 6 | 6 | 80 | 35 | 12 | 3 | 2 |
| 27A600060500S06 | Ø6x50x120-S06 | 6 | 6 | 120 | 50 | 12 | 3 | 2 |
| 27A600060600S06 | Ø6x60x120-S06 | 6 | 6 | 120 | 60 | 12 | 3 | 2 |