


Mandril Máquinas HSS-E CO - Série 650

Categorias

• HSS



Ref.	Descrição	D1	D3	L1	L2	L3
290200006500100	Mandril Máquina HSS-E CO - 1 X 22	1	D	38	22	7
290200006500110	Mandril Máquina HSS-E CO - 1,1 X 24	1,1	D	40	24	10
290200006500120	Mandril Máquina HSS-E CO - 1,2 X 24	1,2	D	40	24	10
290200006500130	Mandril Máquina HSS-E CO - 1,3 X 24	1,3	D	40	24	10
290200006500140	Mandril Máquina HSS-E CO - 1,4 X 24	1,4	D	40	24	10
290200006500150	Mandril Máquina HSS-E CO - 1,5 X 24	1,5	D	40	24	10
290200006500160	Mandril Máquina HSS-E CO - 1,6 X 25	1,6	D	43	25	11
290200006500170	Mandril Máquina HSS-E CO - 1,7 X 25	1,7	D	43	25	11
290200006500180	Mandril Máquina HSS-E CO - 1,8 X 31	1,8	D	49	31	12
290200006500190	Mandril Máquina HSS-E CO - 1,9 X 31	1,9	D	49	31	12
290200006500200	Mandril Máquina HSS-E CO - 2 X 31	2	D	49	31	12
290200006500210	Mandril Máquina HSS-E CO - 2,1 X 31	2,1	D	49	31	12
290200006500220	Mandril Máquina HSS-E CO - 2,2 X 31	2,2	D	49	31	12
290200006500230	Mandril Máquina HSS-E CO - 2,3 X 31	2,3	D	49	31	12
290200006500240	Mandril Máquina HSS-E CO - 2,4 X 38	2,4	D	57	38	18
290200006500250	Mandril Máquina HSS-E CO - 2,5 X 38	2,5	D	57	38	18
290200006500260	Mandril Máquina HSS-E CO - 2,6 X 38	2,6	D	57	38	18
290200006500270	Mandril Máquina HSS-E CO - 2,7 X 38	2,7	D	57	38	18
290200006500280	Mandril Máquina HSS-E CO - 2,8 X 38	2,8	D	57	38	18
290200006500290	Mandril Máquina HSS-E CO - 2,9 X 38	2,9	D	57	38	18
290200006500300	Mandril Máquina HSS-E CO - 3 X 38	3	D	57	38	18
290200006500310	Mandril Máquina HSS-E CO - 3,1 X 38	3,1	D	57	38	18
290200006500320	Mandril Máquina HSS-E CO - 3,2 X 38	3,2	D	57	38	18
290200006500330	Mandril Máquina HSS-E CO - 3,3 X 38	3,3	D	57	38	18
290200006500340	Mandril Máquina HSS-E CO - 3,4 X 38	3,4	D	57	38	18
290200006500350	Mandril Máquina HSS-E CO - 3,5 X 38	3,5	D	57	38	18

Ref.	Descrição	D1	D3	L1	L2	L3
290200006500360	Mandril Máquina HSS-E CO - 3,6 X 38	3,6	D	57	38	18
290200006500370	Mandril Máquina HSS-E CO - 3,7 X 38	3,7	D	57	38	18
290200006500380	Mandril Máquina HSS-E CO - 3,8 X 51	3,8	4	75	51	19
290200006500390	Mandril Máquina HSS-E CO - 3,9 X 51	3,9	4	75	51	19
290200006500400	Mandril Máquina HSS-E CO - 4 X 51	4	4	75	51	19
290200006500410	Mandril Máquina HSS-E CO - 4,1 X 51	4,1	4	75	51	19
290200006500420	Mandril Máquina HSS-E CO - 4,2 X 51	4,2	4	75	51	19
290200006500430	Mandril Máquina HSS-E CO - 4,3 X 55	4,3	4,5	80	55	21
290200006500440	Mandril Máquina HSS-E CO - 4,4 X 55	4,4	4,5	80	55	21
290200006500450	Mandril Máquina HSS-E CO - 4,5 X 55	4,5	4,5	80	55	21
290200006500460	Mandril Máquina HSS-E CO - 4,6 X 55	4,6	4,5	80	55	21
290200006500470	Mandril Máquina HSS-E CO - 4,7 X 55	4,7	4,5	80	55	21
290200006500480	Mandril Máquina HSS-E CO - 4,8 X 60	4,8	5	86	60	23
290200006500490	Mandril Máquina HSS-E CO - 4,9 X 60	4,9	5	86	60	23
290200006500500	Mandril Máquina HSS-E CO - 5 X 60	5	5	86	60	23
290200006500510	Mandril Máquina HSS-E CO - 5,1 X 60	5,1	5	86	60	23
290200006500520	Mandril Máquina HSS-E CO - 5,2 X 60	5,2	5	86	60	23
290200006500530	Mandril Máquina HSS-E CO - 5,3 X 60	5,3	5	86	60	23
290200006500540	Mandril Máquina HSS-E CO - 5,4 X 66	5,4	5,5	93	66	26
290200006500550	Mandril Máquina HSS-E CO - 5,5 X 66	5,5	5,5	93	66	26
290200006500560	Mandril Máquina HSS-E CO - 5,6 X 66	5,6	5,5	93	66	26
290200006500570	Mandril Máquina HSS-E CO - 5,7 X 66	5,7	5,5	93	66	26
290200006500580	Mandril Máquina HSS-E CO - 5,8 X 66	5,8	5,5	93	66	26
290200006500590	Mandril Máquina HSS-E CO - 5,9 X 73	5,9	6	101	73	28
290200006500600	Mandril Máquina HSS-E CO - 6 X 73	6	6	101	73	28
290200006500610	Mandril Máquina HSS-E CO - 6,1 X 73	6,1	6	101	73	28
290200006500620	Mandril Máquina HSS-E CO - 6,2 X 73	6,2	6	101	73	28
290200006500630	Mandril Máquina HSS-E CO - 6,3 X 73	6,3	6	101	73	28
290200006500640	Mandril Máquina HSS-E CO - 6,4 X 73	6,4	6	101	73	28
290200006500650	Mandril Máquina HSS-E CO - 6,5 X 73	6,5	6	101	73	28
290200006500660	Mandril Máquina HSS-E CO - 6,6 X 73	6,6	6	101	73	28
290200006500670	Mandril Máquina HSS-E CO - 6,7 X 73	6,7	6	101	73	28
290200006500680	Mandril Máquina HSS-E CO - 6,8 X 80	6,8	7	109	80	31
290200006500690	Mandril Máquina HSS-E CO - 6,9 X 80	6,9	7	109	80	31
290200006500700	Mandril Máquina HSS-E CO - 7 X 80	7	7	109	80	31
290200006500710	Mandril Máquina HSS-E CO - 7,1 X 80	7,1	7	109	80	31
290200006500720	Mandril Máquina HSS-E CO - 7,2 X 80	7,2	7	109	80	31
290200006500730	Mandril Máquina HSS-E CO - 7,3 X 80	7,3	7	109	80	31
290200006500740	Mandril Máquina HSS-E CO - 7,4 X 80	7,4	7	109	80	31
290200006500750	Mandril Máquina HSS-E CO - 7,5 X 80	7,5	7	109	80	31
290200006500760	Mandril Máquina HSS-E CO - 7,6 X 86	7,6	8	117	86	33
290200006500770	Mandril Máquina HSS-E CO - 7,7 X 86	7,7	8	117	86	33
290200006500780	Mandril Máquina HSS-E CO - 7,8 X 86	7,8	8	117	86	33

Ref.	Descrição	D1	D3	L1	L2	L3
290200006500790	Mandril Máquina HSS-E CO - 7,9 X 86	7,9	8	117	86	33
290200006500800	Mandril Máquina HSS-E CO - 8 X 86	8	8	117	86	33
290200006500810	Mandril Máquina HSS-E CO - 8,1 X 86	8,1	8	117	86	33
290200006500820	Mandril Máquina HSS-E CO - 8,2 X 86	8,2	8	117	86	33
290200006500830	Mandril Máquina HSS-E CO - 8,3 X 86	8,3	8	117	86	33
290200006500840	Mandril Máquina HSS-E CO - 8,4 X 86	8,4	8	117	86	33
290200006500850	Mandril Máquina HSS-E CO - 8,5 X 86	8,5	8	117	86	33
290200006500860	Mandril Máquina HSS-E CO - 8,6 X 86	8,6	8	117	86	33
290200006500870	Mandril Máquina HSS-E CO - 8,7 X 86	8,7	8	117	86	33
290200006500880	Mandril Máquina HSS-E CO - 8,8 X 86	8,8	8	117	86	33
290200006500890	Mandril Máquina HSS-E CO - 8,9 X 86	8,9	8	117	86	33
290200006500900	Mandril Máquina HSS-E CO - 9 X 86	9	8	117	86	33
290200006500910	Mandril Máquina HSS-E CO - 9,1 X 86	9,1	8	117	86	33
290200006500920	Mandril Máquina HSS-E CO - 9,2 X 86	9,2	8	117	86	33
290200006500930	Mandril Máquina HSS-E CO - 9,3 X 86	9,3	8	117	86	33
290200006500940	Mandril Máquina HSS-E CO - 9,4 X 86	9,4	8	117	86	33
290200006500950	Mandril Máquina HSS-E CO - 9,5 X 86	9,5	8	117	86	33
290200006500960	Mandril Máquina HSS-E CO - 9,6 X 99	9,6	10	133	99	38
290200006500970	Mandril Máquina HSS-E CO - 9,7 X 99	9,7	10	133	99	38
290200006500980	Mandril Máquina HSS-E CO - 9,8 X 99	9,8	10	133	99	38
290200006500990	Mandril Máquina HSS-E CO - 9,9 X 99	9,9	10	133	99	38
290200006501000	Mandril Máquina HSS-E CO - 10 X 99	10	10	133	99	38
290200006501010	Mandril Máquina HSS-E CO - 10,1 X 99	10,1	10	133	99	38
290200006501020	Mandril Máquina HSS-E CO - 10,2 X 99	10,2	10	133	99	38
290200006501030	Mandril Máquina HSS-E CO - 10,3 X 99	10,3	10	133	99	38
290200006501040	Mandril Máquina HSS-E CO - 10,4 X 99	10,4	10	133	99	38
290200006501050	Mandril Máquina HSS-E CO - 10,5 X 99	10,5	10	133	99	38
290200006501060	Mandril Máquina HSS-E CO - 10,6 X 99	10,6	10	133	99	38
290200006501070	Mandril Máquina HSS-E CO - 10,7 X 99	10,7	10	133	99	38
290200006501080	Mandril Máquina HSS-E CO - 10,8 X 99	10,8	10	133	99	38
290200006501090	Mandril Máquina HSS-E CO - 10,9 X 99	10,9	10	133	99	38
290200006501100	Mandril Máquina HSS-E CO - 11 X 99	11	10	133	99	38
290200006501110	Mandril Máquina HSS-E CO - 11,1 X 99	11,1	10	133	99	38
290200006501120	Mandril Máquina HSS-E CO - 11,2 X 99	11,2	10	133	99	38
290200006501130	Mandril Máquina HSS-E CO - 11,3 X 99	11,3	10	133	99	38
290200006501140	Mandril Máquina HSS-E CO - 11,4 X 106	11,4	12	151	106	44
290200006501150	Mandril Máquina HSS-E CO - 11,5 X 106	11,5	12	151	106	44
290200006501160	Mandril Máquina HSS-E CO - 11,6 X 106	11,6	12	151	106	44
290200006501170	Mandril Máquina HSS-E CO - 11,7 X 106	11,7	12	151	106	44
290200006501180	Mandril Máquina HSS-E CO - 11,8 X 106	11,8	12	151	106	44
290200006501190	Mandril Máquina HSS-E CO - 11,9 X 106	11,9	12	151	106	44
290200006501200	Mandril Máquina HSS-E CO - 12 X 106	12	12	151	106	44
290200006501250	Mandril Máquina HSS-E CO - 12,5 X 106	12,5	12	151	106	44

Ref.	Descrição	D1	D3	L1	L2	L3
290200006501300	Mandril Máquina HSS-E CO - 13 X 106	13	12	151	106	44
290200006501350	Mandril Máquina HSS-E CO - 13,5 X 110	13,5	14	160	110	47
290200006501400	Mandril Máquina HSS-E CO - 14 X 110	14	14	160	110	47
290200006501450	Mandril Máquina HSS-E CO - 14,5 X 112	14,5	14	162	112	50
290200006501500	Mandril Máquina HSS-E CO - 15 X 112	15	14	162	112	50
290200006501550	Mandril Máquina HSS-E CO - 15,5 X 117	15,5	16	170	117	52
290200006501600	Mandril Máquina HSS-E CO - 16 X 117	16	16	170	117	52
290200006501650	Mandril Máquina HSS-E CO - 16,5 X 122	16,5	16	175	122	54
290200006501700	Mandril Máquina HSS-E CO - 17 X 122	17	16	175	122	54
290200006501750	Mandril Máquina HSS-E CO - 17,5 X 129	17,5	16	182	129	56
290200006501800	Mandril Máquina HSS-E CO - 18 X 129	18	16	182	129	56
290200006501850	Mandril Máquina HSS-E CO - 18,5 X 136	18,5	16	189	136	58
290200006501900	Mandril Máquina HSS-E CO - 19 X 136	19	16	189	136	58
290200006501950	Mandril Máquina HSS-E CO - 19,5 X 142	19,5	16	195	142	60
290200006502000	Mandril Máquina HSS-E CO - 20 X 142	20	16	195	142	60

